



More Precision

wireSENSOR // Draw-wire displacement sensors





Robust miniature sensors




- Miniature design
- Optional IP67 (MPW)
- For fast measurement and harsh environments

Model MP / MPW








Measuring range (mm)	A (mm)	B (mm)
100 / 300 / 500 / 1000-MP	15.7	82.5
100 / 300 / 500 / 1000-MPW	15.7	86.5


Model		WDS-100 MP(W)	WDS-300 MP(W)	WDS-500 MP(W)	WDS-1000 MP(W)	
Output		Р				
Measuring range		100mm	300mm	500mm	1000mm	
Linearity	±0.1% FSO	-	-	±0.5mm	±1mm	
	±0.25% FSO	-	±0.75mm	-	-	
	±0.5% FSO	±0.5mm	-	-	-	
Resolution		0.15mm 0.2mm towards infinity			sinfinity	
Sensor element		wire potentiometer hybrid potentiometer			entiometer	
Temperature range		-20 °C +80 °C				
Material	housing	aluminum				
Material	draw-wire	stainless steel (ø 0.45mm)				
Wire mounting		thread M4				
Sensor mounting		swivel flange in two axes 180° / 360°				
Wire acceleration		approx. 30g				
Wire retraction force (min)		7N	7N	6.5N	5N	
Wire extension force (max)		8.5N	8.5N	8.5N	8N	
Protection class	series MP	IP65				
FIOLECTION Class	series MPW	IP67				
Vibration		20g, 20Hz - 2kHz				
Mechanical shock		50g, 10ms				
Electrical connection			integrated cable,	axial, 3-leads, 1m		
Weight			approx	270g		

FSO = Full Scale Output
Specifications for analog outputs on page 51.

Article description



Accessories:	
WE-xxx-M4	Wire extension with M4-wire connection, x=length
WE-xxxx-Clip	Wire extension with eyelet, x=length
TR1-WDS	Pulley wheel, adjustable
TR3-WDS	Pulley wheel, fixed
GK1-WDS	Attachment head for M4
MH1-WDS	Magnetic holder for wire mounting
MH2-WDS	Magnetic holder for sensor mounting
MT-60-WDS	Mounting clamp for WDS-P60
FC8	Female connector for WDS, 8-pin
FC8/90	Female connector 90° for WDS
PC 3/8-WDS	Sensor cable, length 3m
PS 2020	(Power Supply 24 V / 2,5 A, Input 100 - 240 VAC, output 24 VDC / 2.5 A, for snap in mounting on DIN 50022 rail)
WDS-MP60	Mounting plate for P60 sensors





Installation information:

Wire attachment: The free return of the measurement wire is not permissible and it is essential that this is avoided during installation.

Wire exit angle:

When mounting a draw-wire displacement sensor, a straight wire exit ($\pm 3^{\circ}$ tolerance) must be taken into account. If this tolerance is exceeded, increased material wear on the wire and at the wire aperture must be expected.





Mounting plate WDS-MP60

Potentiometric output	(P)				
Supply voltage Resistance Temperature coefficient	max. 32VDC at 1kOhm / 1 Wmax 1kOhm ±10% (potentiometer) ±0.0025% FSO/°C	5 6 4 4 7 7 6 sensor side		2 CW -> (1)	3881
		1 = input + 2 = grounding 3 = signal	white = input + brown = grounding green = signal	1 = input + 2 = signal 3 = grounding	@ WIPER

Voltage output (U)				
Supply voltage	14 27VDC (non stabilized)			
Current consumption	max. 30mA	2		
Output voltage	0 10VDC Option 0 5 / ±5V	5 4 3 8 1 7 i 6 sensor side 1 = supply 2 = grounding 3 = signal 4 = ground		
Load impedance	>5kOhm			
Signal noise	0.5mV _{eff}			
Temperature coefficient	±0.005% FSO/°C			
Electromagnetic compatibility (EMC)	EN 61000-6-4 EN 61000-6-2		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Adjustment ranges (if s	supported by the model)			1117
Zero	±20% FSO		3 = signal green = signal	
Sensitivity	±20%			

Current Output (I)			
Supply voltage	14 27VDC (non stabilized)		
Current consumption	max. 35mA		
Output current	4 20mA		
Load	<600Ohm	5 • 2 4	
Signal noise	<1,6 μ A _{eff}		
Temperature coefficient	±0.01% FSO/°C	8 6	
Electromagnetic compatibility (EMC)	EN 61000-6-4 EN 61000-6-2	sensor side	
Adjustment range (if su	ipported by the model)		
Zero	±18% FSO	1 = supply	white = supply
Sensitivity	±15%	2 = grounding	brown = grounding



APPLIED MEASUREMENTS LTD.

Transducer Specialists...

appmeas.co.uk | info@appmeas.co.uk | +44 (0) 118 981 7339